

第64表 平成21年以降における住宅の耐震診断の有無(3区分), 建築の時期(9区分), 購入・新築・建て替え等(7区分)別持ち家数—市区

Table 64. Owned Houses by Situation of Seismic Diagnosis of Dwellings, etc. since 2009 (3 Groups), Year of Construction (9 Groups) and Purchase, Construction, Reconstruction, etc. of Dwelling (7 Groups) - Shi and Ku

平成21年以降における住宅の耐震診断の有無(3区分), 建築の時期(9区分)  Situation of seismic diagnosis of dwellings, etc. since 2009 (3 Groups) and year of construction (9 Groups)	総数  Total	新築の住宅を購入 Purchased newly built houses			中古住宅を 購入  Purchased used-houses	新築 (建て替え を除く)  Newly built (excluding rebuilt)	建て替え  Rebuilt	相続・贈与 で取得  Acquired by inheritance or grant	その他  Others	
		総数  Total	都市再生機構 (UR)・公社 など  From Urban Renaissance Agency or public corporations							民間  From private companies
<b>204 鎌倉市</b>										
持ち家総数 1)	49,460	10,800	220	10,590	7,690	16,960	8,180	3,170	2,670	
昭和35年以前	2,280	40	-	40	370	540	190	780	370	
昭和36年～45年	3,200	180	20	160	380	1,230	400	610	410	
昭和46年～55年	9,560	1,350	10	1,340	2,080	3,450	1,250	740	690	
昭和56年～平成2年	8,430	1,160	-	1,160	2,150	2,590	1,790	350	400	
平成3年～7年	3,600	520	-	520	760	1,240	790	100	190	
平成8年～12年	6,020	1,540	180	1,350	660	2,130	1,310	180	200	
平成13年～17年	7,610	3,730	-	3,730	590	2,140	890	140	120	
平成18年～22年	5,420	1,710	-	1,710	300	2,300	830	80	200	
平成23年～25年9月	1,990	490	-	490	30	960	420	60	20	
耐震診断をした 1)	5,060	1,580	-	1,580	750	1,710	690	130	210	
昭和35年以前	220	-	-	-	20	70	30	40	60	
昭和36年～45年	170	-	-	-	20	70	30	30	10	
昭和46年～55年	870	110	-	110	240	360	70	30	50	
昭和56年～平成2年	330	40	-	40	100	80	120	-	-	
平成3年～7年	250	20	-	20	160	20	40	20	-	
平成8年～12年	500	40	-	40	70	250	60	-	80	
平成13年～17年	1,130	900	-	900	90	80	40	-	10	
平成18年～22年	720	230	-	230	10	390	90	-	-	
平成23年～25年9月	810	240	-	240	-	360	220	-	-	
耐震性が確保されていた 1)	4,340	1,490	-	1,490	550	1,410	640	50	180	
昭和35年以前	140	-	-	-	-	40	30	20	60	
昭和36年～45年	80	-	-	-	-	30	30	-	10	
昭和46年～55年	440	40	-	40	160	130	70	20	20	
昭和56年～平成2年	280	40	-	40	100	80	70	-	-	
平成3年～7年	230	20	-	20	150	20	40	20	-	
平成8年～12年	500	40	-	40	70	250	60	-	80	
平成13年～17年	1,100	900	-	900	70	80	40	-	10	
平成18年～22年	720	230	-	230	10	390	90	-	-	
平成23年～25年9月	810	240	-	240	-	360	220	-	-	
耐震性が確保されていなかった 1)	730	80	-	80	190	290	50	80	30	
昭和35年以前	80	-	-	-	20	30	-	20	-	
昭和36年～45年	90	-	-	-	20	40	-	30	-	
昭和46年～55年	430	70	-	70	90	230	-	20	30	
昭和56年～平成2年	50	-	-	-	-	-	50	-	-	
平成3年～7年	20	-	-	-	20	-	-	-	-	
平成8年～12年	-	-	-	-	-	-	-	-	-	
平成13年～17年	20	-	-	-	20	-	-	-	-	
平成18年～22年	-	-	-	-	-	-	-	-	-	
平成23年～25年9月	-	-	-	-	-	-	-	-	-	
耐震診断をしていない 1)	44,400	9,230	220	9,010	6,940	15,250	7,490	3,040	2,460	
昭和35年以前	2,060	40	-	40	350	470	170	730	310	
昭和36年～45年	3,030	180	20	160	360	1,160	360	580	390	
昭和46年～55年	8,700	1,240	10	1,230	1,840	3,100	1,170	710	650	
昭和56年～平成2年	8,100	1,120	-	1,120	2,050	2,510	1,670	350	400	
平成3年～7年	3,350	500	-	500	600	1,220	750	80	190	
平成8年～12年	5,520	1,500	180	1,320	590	1,880	1,250	180	120	
平成13年～17年	6,480	2,820	-	2,820	490	2,060	850	140	100	
平成18年～22年	4,710	1,480	-	1,480	290	1,910	740	80	200	
平成23年～25年9月	1,180	260	-	260	30	610	200	60	20	

1) 建築の時期「不詳」を含む。

1) Including year of construction "Not reported".